

### **MCT-7MA 7" Version V1.2 release notes/updates 01-10-2024**

1. Features and functionality updated to latest MCT-4MA release.

Validated via MCT-7MA SVP Addendum R1.

### **MCT-7MA 7" Version V1.1.1 release notes/updates 08-24-2021**

1. Runtime bug corrected when output2 programmed for event output when manual or auto-tune mode entered. Outputs would de-energized when either mode was entered and not energized when either mode was exited. This only occurred if output2 on PCM/B42 was programmed for "event" outputs. It did not affect any other output 2 program modes.

No SVP re-run required with updated verified with engineering test protocol

### **MCT-7MA 7" Version V1.1 release notes/updates 08-15-2021**

1. V1.1 production release. Programmable single setpoint timer addition added to system. Programmable timer cycle activates "Event 1" for x-time with shutoff of event after timer times out. See SDLC for SVP testing.

Validated via protocol 1, steps 10 and 11 and protocol 27 in configurator SVP R6

Validated via protocols 85 through 87 in GUI Runtime SVP R6

### **MCT-7MA 7" Version V1.0 release notes/updates 07-29-2021**

1. V1.0 production release. No regressions found in DVR4\_V0.4.

### **MCT-7MA 7" Version DVR4\_V0.4 release notes/updates 07-25-2021**

1. DVR4\_V0.4 release for lifecycle regression testing from bugs found in DVR3.
2. Logic code bug corrected to properly evaluate all trigger inputs during logic calculations, output set/reset. Validated via protocol 17 steps 70 through 92 in Configurator SVP R5
3. Auto log off period (minutes) max value entry set to 365 when should be 1440. Validated via protocol 76 step 1 in GUI SVP R5.
4. Text error in GUI SVP caused protocol 37 to fail (operator event dialog error). While not a code error, re-run protocol 37 since SVP was updated to R5.

### **MCT-7MA 7" Version DVR3\_V0.3 release notes/updates 06-06-2021**

1. DVR3\_V0.3 release for complete lifecycle testing. All protocols to be run for configuration and runtime using configuration SVP R4 and GUI SVP R3. DVR2\_V0.2 did not get released for testing due to regressions found in 4.3" testing.

### **MCT-7MA 7" Version DVR2\_V0.2 release notes/updates 04-09-2021**

1. DVR2\_V0.2 release for lifecycle (SDLC) testing. DRV1\_V0.1 did not get released due to configuration bug found during internal testing with programming of IO expansion module events. Max count of 16 events displayed an error when changing event types allowed (Manual Only, Math/Logic). Bug corrected in DVR2\_V0.2 with full SDLC testing performed.

#### **MCT-7MA 7" Version DVR1\_V0.1 release notes/updates 02-13-2021**

1. DVR1\_V0.1 release for field and full lifecycle testing. See SDLC for details. Based on MCT-4MA V1.1 with IO expander added.